



DOCKET NO.: P05098
CLIENT NO.: NATI15-05098
Customer No.: 23990

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Certificate

FEB 22 2006

of Correction

In re U.S. Patent No. : 6,868,503 B1
Inventor(s) : Dragan Maksimovic et al.
Issued : March 15, 2005
Title : ADAPTIVE VOLTAGE SCALING DIGITAL PROCESSING
COMPONENT AND METHOD OF OPERATING THE SAME

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF MAILING BY FIRST CLASS MAIL

Sir:

The undersigned hereby certifies that the following documents:

1. Request for Certificate of Correction (in duplicate);
2. Certificate of Correction (in duplicate); and
3. A postcard receipt

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on February 13, 2006.

Date: Feb 13, 2006

Kathy Hamilton
Mailer

Date: Feb 13, 2006

William Munck
William A. Munck
Reg. No. 39,308

P.O. Drawer 800889
Dallas, Texas 75380
Phone: (972) 628-3600
Fax: (972) 628-3616
E-mail: wmunck@davismunck.com

FEB 22 2006

DOCKET NO.: P05098
CLIENT NO.: NATI15-05098
Customer No.: 23990



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No. : 6,868,503 B1

Inventor(s) : Dragan Maksimovic et al.

Issued : March 15, 2005

Title : ADAPTIVE VOLTAGE SCALING DIGITAL PROCESSING
COMPONENT AND METHOD OF OPERATING THE SAME

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

ATTORNEY DOCKET NO.: P05098
PATENT NO.: 6,868,503 B1

Respectfully submitted,

DAVIS MUNCK, P.C.

Date: Feb 13, 2006



William A. Munck
Registration No. 39,308

P.O. Drawer 800889
Dallas, Texas 75380
Telephone: (972) 628-3600
Facsimile: (972) 628-3616
E-mail: wmunck@davismunck.com

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,868,503 B1

DATED : March 15, 2005

INVENTOR(S) : Dragan Maksimovic, Sandeep Dhar, Bruno Kranzen and Ravindra Ambatipudi

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8, line 39, delete "ar" and replace with – an – and delete "a*1" and replace with – a≠1 –;

Column 9, line 42, delete "(FP)" and replace with – (FF) –;

Column 9, line 66, delete "μ" and replace – 11 –.

MAILING ADDRESS OF SENDER:

Docket Clerk
P.O. Drawer 800889
Dallas, Texas 75380

PATENT NO. 6,868,503 B1

No. of additional copies

→ 1

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

FEB 22 2006